

Notification o Hazardous Waste Site

United States **Environmental Protection** Agency Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must which applies, be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of

18. D Other (Specify)

	,	ò	310608	W#81	165-000-001-342	
į	Person Required to Notify: Enter the name and address of the person or organization required to notify.		Name MONS	SANTO COMPANY		
					800 N. LINBERGH WILL	
				G. Krummrich Pl	ant	
			City -Saux	etsT. Louis	State MO Zip Code 6 201	
 3	Site Location:			······································	(Pump #1)	
	Enter the common name (if knoold,) and actual location of the site		Name of Site W. (3. Krummrich Pl	ant	
			Street Near Levex Rd + Monsanto Ave			
ILD980498059			City Sauget CountySt.Clair State IL Zip Code 62201			
;	Person to Contact:			Sinige Pich	ard, Environmantal Engineer	
	Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.		· ·			
			Phone (618) 271-5835			
	SSUMMO OF THE COMM.					
)	Dates of Waste Handling:					
	Enter the years that you estimate treatment, storage, or disposal beended at the site.		From (Year) Unknow.	yn _{To (Year)} 1957		
 :	Waste Type: Choose the optio	n you pre	efer to complete			
	Option I: Select general waste typyou do not know the general waste encouraged to describe the site in	le types or	sources, you are Resource Conservation and Recovery Act (RCRA) Section 30		on and Recovery Act (RCRA) Section 3001	
	General Type of Waste: Place an X in the appropriate boxes. The categories listed cverlap. Check each applicable category.	Source o Place an boxes.	f Waste: X in the appropriate	EPA has assigned a listed in the regulate appropriate four-dignithe list of hazardous contacting the EPA #	Specific Type of Waste: EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.	
	1. 🛣 Organics	1. 🗆 Mi	•	1000150.		
	2. X Inorganics		nstruction			
	3. X Solvents	3. □ Te>				
	4. 🗇 Pestic des	4. ☐ Fer			,	
	5. X Heavy metals	•	per/Printing			
	6. XI Acids		ather Tanning			
	7. D Bases		n/Steel Foundry			
	8. ☐ PCBs		emical, General			
	9. Mixed Municipal Waste		ting/Polishing			
	10. Unknown		litary/Ammunition			
	11. 🗆 Other (Specify)		ctrical Conductors			
			insformers	: i	•	
			lity Companies			
			nitary/Refuse	ມູກການ	7	
		15. D Ph			JUN -8 81	
	EPA Region 5 Records Ctr.		o/Hospital	1	· 00	
	1 400 11 A 41 KBA 1 BANG MANA 1560 BANG 1870 1870	17. 🗆 Un	KNOWN		V ,	

Form Approved DMB No. 1007-0138 EPA Form 8900 1

286733